

Details

Features and Updates

Plumbed for gas (natural)

Tankless water heater

Gutters 2 year old

Roof 2 years old and is transferable for 23 more years

Insulation all redone 2 years ago

Plumbing is pex and a couple years old

½ sewer line kitchen/laundry room

HVAC after Imelda

LVP flooring and carpet

Master Bath redid and has a soaking tub and separate shower

Anderson windows a few years ago

A little water came in when Imelda happened

Under the carport is 3 storage area closets all with power

Cameras will stay and are amazon blink cameras

Front door is real iron and an antique

Painted the house 2 years ago

Gas fireplace in living room and formal dining room is a show one but has a gas hookup also

Big TV in living room will stay/ Washer and Dryer will stay/ Fridge will stay

Carpet is 6 years old