




Note: Minimum distance of 5' between dwellings per plat.

Note: All bearings shown hereon are based on the record plat indicated below.

Note: Restrictive covenants as recorded in Slide No(s). 1919/A and 1919/B FBCPR and V-1575, P-1; V-1575, P-78; V-1818, P-589; V-2227, P-35; V-2227, P-118 and V-2323, P-1974 and CF#'s 9542492, 9675788, 9703952, 9828370, 1999104957, 1999111837, 2000020728, 2000090333, 2001012911, 2002008752 CCORFBC.

BUYER: ROBERT LANDRY & SHELLEY LANDRY

3302 PIONEER BEND LANE

DESCRIBED PROPERTY:

Lot Ninety-One (91), in Block Two (2), of CINCO RANCH EQUESTRIAN VILLAGE SECTION THREE (3), a subdivision in Harris and Fort Bend Counties, Texas, according to the map or plat thereof recorded in Film Code 431025, of the Map Records of Harris County, Texas, and in Slide No(s). 1919/A and 1919/B, of the Plat Records of Fort Bend County, Texas. (Subject property lies wholly in Fort Bend County, Texas)



1610 South Gordon • Alvin, Texas 77511
(281) 388-1169 • Fax: (281) 388-0317

G.F. 06300448

Date: 5/3/08

Job: 38055



Registered Professional Land Surveyor
Texas Registration No. 4901

I, Steven H. Stafford, Registered Professional Land Surveyor, State of Texas, do hereby certify that the above Plat represents an actual survey made on the ground on this day under my supervision, and there are no discrepancies, conflicts, shortages in area or boundary lines, or any encroachments, or overlapping of improvements, to the best of my knowledge and belief, except as shown herein.

Note: As this information is based on graphic plotting only, we assume no responsibility for exact flood zone determination.
Note: There are no natural drainage courses on this property.
Note: This property does not lie in a flood hazard zone according to FEMA.

48157C0105 J 1/3/97 Zone "X"

GC