

Henley Plumbing LLC

Office@Henleyplumbing.net

16320 Whippoorwill Road

Navasota, TX 77868

713 828-1501

4/21/25

PROPERTY 28010 Fulshear Plantation Dr. Fulshear, TX 77042

A hydrostatic test was performed in the main sewer line, the details of any findings are described here : A 4" test ball was inserted into the main clean out to block any water from draining into the city drain.

- A. The entire sewer line was filled from the outside through the clean-out, and held for a period of 15 minutes.
- B. At the time of completion, it was determined that the water level held at the top of the clean out, verifying that the pipes under the house ARE in good working order and there is not a water loss AT THIS TIME.

Jay P. Henley, RMP #18558

Texas State Board of Plumbing Examiners, 929 East 41st St., Austin, TX 78751

Office 512-450-0637 Fax 512-936-5200 www.tsbpe.state.tx.us