

Javier Perez

314 Roofing Solutions

Apr 28, 2025 | 13 Photos



2506 Seedling St



2506 Seedling St



Project: 2506 Seedling St
 Date: Apr 22, 2025, 10:32 AM
 Creator: Angel Gomez

2 Roof Covering Materials

SHINGLES: LIFTED/CUPPED
RIGHT
 Observed buckled/lifted shingles on the roof covering. This condition is where the shingles are lifted or are not laying flat due to wrinkling of the underlayment or a shingle issue. High humidity and moisture issues at decking can also contribute to this condition. Recommend further evaluation by a roofing contractor to determine the extent of necessary repair.

[SEE LESS](#)

Roofing Professional

2.3.2 - C. Roof Covering Materials

FLASHING: LOOSE/RAISED FLASHING
RIGHT, LEFT
 Raised or loose flashing areas were observed around the roof covering. This condition leaves the covering exposed to potential moisture or pest intrusion. Recommend all areas be evaluated and secured/sealed as needed.

Roofing Professional

Project: 2506 Seedling St
 Date: Apr 28, 2025, 12:01 PM
 Creator: Javier Perez



Project: 2506 Seedling St
 Date: Apr 22, 2025, 9:03 AM
 Creator: Angel Gomez



Project: 2506 Seedling St
Date: Apr 22, 2025, 9:06 AM
Creator: Angel Gomez



Project: 2506 Seedling St
Date: Apr 22, 2025, 9:12 AM
Creator: Angel Gomez




Project: 2506 Seedling St
Date: Apr 22, 2025, 9:16 AM
Creator: Angel Gomez



Project: 2506 Seedling St
Date: Apr 22, 2025, 9:17 AM
Creator: Angel Gomez




Project: 2506 Seedling St
Date: Apr 22, 2025, 9:18 AM
Creator: Angel Gomez



Project: 2506 Seedling St
Date: Apr 22, 2025, 9:40 AM
Creator: Angel Gomez



Project: 2506 Seedling St
Date: Apr 22, 2025, 9:47 AM
Creator: Angel Gomez



Project: 2506 Seedling St
Date: Apr 22, 2025, 9:59 AM
Creator: Angel Gomez



Project: 2506 Seedling St
Date: Apr 22, 2025, 10:07 AM
Creator: Angel Gomez

13



Project: 2506 Seedling St
Date: Apr 22, 2025, 10:18 AM
Creator: Angel Gomez