



Owner Updates & Improvements



- Exterior deck and stairs have been rebuilt
- Damaged siding has been repaired and replaced
- Plumbing and electrical systems have been updated
- HVAC system installed for downstairs unit; upstairs HVAC has been serviced and updated
- New Water heater added
- Bathrooms in both units have been updated, including tile, vanities, flooring, tubs, and fixtures
- Kitchens in both units have been updated with quartz countertops and cabinetry
- Flooring updated throughout with LVP in living areas and tile in bathrooms
- Interior improvements include updated sheetrock, baseboards, trim, and doors
- Interior and exterior of the home, including carport, have been freshly painted