

## Sprinkler System Inspection

---

Weichert Workforce Mobility  
5 Wood Hollow Road  
Parsippany, NJ 07054

04/20/2026  
Client File # M-C-00429476-1  
FICS File # 3062943

**Inspection Address**

katherine O'Connor  
626 Longview Drive  
Sugar Land, Texas 77478

In accordance with your request a Sprinkler Inspection was conducted on **04/20/2026** at the above captioned property. All visible components of the 6 zone sprinkler system were evaluated. The following is a summary of the inspector's findings.

CONDITION OF COMPONENTS	
<b>Automatic Timer</b>	Acceptable
<b>Manual Controls</b>	Acceptable
<b>Shut Off/Draining Valves</b>	Acceptable
<b>Individual Zones/Pop up Heads</b>	Acceptable
<b>Water Pressure Flow</b>	Acceptable

If you should have any questions, please do not hesitate to contact me.

Sincerely,



Frank Waslewski Jr.  
Director of Account Management

**ADDITIONAL PHOTOS**



Overviews



sprinkler



sprinkler



sprinkler



sprinkler



sprinkler