




LEGEND

- These standard symbols will be found in the drawing.
- FOUND MONUMENT
 - SET 5/8" I.R. W/CAP
 - ▲ A/C
 - GAS METER
 - ★ LIGHT POLE
 - MANHOLE
 - ⊗ TELE PEDESTAL
 - ⊙ CABLE BOX
 - ⊕ WATER METER
 - ▨ COVERED AREA
 - ▭ CONCRETE
 - WROUGHT IRON FENCE
 - - - - - WOOD FENCE
 - - - - - EASEMENT/BUILDING LINE

NOTES:
 1. TO SHOW ADDITIONAL BOUNDARY - 11/20/2017 SURVEYOR DID NOT BEARING ORIENTATION BASED ON SOUTH BEARING ORIENTATIONS SHOWN HEREON ARE NOT TO BE USED. BEARINGS ORIENTATIONS SHOWN HEREON ARE NOT TO BE USED. FLOOD INFORMATION PROVIDED ONLY BE USED TO SET PERMITS. ANY ACTION SHOULD BE TAKEN TO SET PERMITS AND NOT TO BE USED TO SET PERMITS. WE ARE NOT RESPONSIBLE FOR THE RESULTS OF THE PERMITS.

LOT 3 & RESTRICTED RESERVE "D"
 RECD: 2
 COUNTY: 6
 SUBDIVISION: WIMBLETON FALLS
 SF: ABSTRACT: 1
 TITLE COMPANY: DONNELLY SURVEY, A-233
 PURCHASER: THOMAS MARTIN BARNES, JR. & LORI JEAN NEILL BARNES
 ADDRESS: 24511 EMERALD POOL FALLS DRIVE TOMBALL, TX 77375

DAVID E. KING
 11-21-17
 KING'S LAND SURVEYING SOLUTIONS, LLC
 318 CORNER STREET #30 SPRING, TX 77373 (281)306-8000



1. David E. King, Sr., Texas Registered Professional Surveyor Number 4503, hereby certifies that he is the author of this survey and that he is duly licensed under my direction, this survey from an actual survey on the ground by me or a duly licensed Professional Surveyor. I am not responsible for the accuracy of this survey unless I have signed and sealed this survey with my hand and official seal and signature.