

Sample Testing and Reporting Record

Date test performed: 1-21-26 ☐ Routine ☐ Repair ☒ Other _____

Owners Name: Brody Cobb

Property (OSSF) Address: 163 Byrd Salyer Rd Bay City, Texas

Person Performing Inspection: Jason Ludwig

Maintenance Provider: Sure'Nuff Septic Services, 3744 CR 126 Van Vleck, Texas 979 557-3017

<u>Inspected Items</u>	<u>Operational</u>	<u>Inoperative</u>
Aerators	<u>SAT</u>	_____
Filters	<u>SAT</u>	_____
Irrigation Pumps	<u>SAT</u>	_____
Recirculation Pumps	<u>N/A</u>	_____
Disinfection Device	<u>SAT</u>	_____
Chlorine Supply	<u>Unsat</u>	_____
Electrical Circuits	<u>SAT</u>	_____
Distribution System	<u>SAT</u>	_____
Sprayfield Vegetation/Seeding (if applicable)	<u>SAT</u>	_____
Other as Noted _____	_____	_____

Repairs to the system (list all components replaced):

Tests required and results:

	<u>Test</u>	<u>Required Results</u>	<u>Test Method</u>
	Yes / No	mg/l, mpn/100 ml, or trace	
BOD (Grab)	<u>No</u>	_____	_____
TSS (Grab)	<u>No</u>	_____	_____
Cl ₂ (Grab)	<u>Yes</u>	<u>0</u>	<u>DPD</u>
Fecal Coliform	<u>No</u>	_____	_____

Date(s) responded to owner complaints during reporting period (attach copy of complaint and findings): _____

General comments or recommendations:

System in condition. Alarms were tested satisfactory. Floats were tested satisfactory. Aerator was providing sufficient airflow. The sprinklers were manually tested with no issues. The sludge level in the pump tank and clarifier chamber were high. Recommend having the system pumped. The union on the discharge pump to the sprinklers is leaking(This does not impact performance).

System did not have any chlorine. The control panel was in good condition. See attached pictures


Access ports secured after the maintenance and inspection activities were completed: ☒ Yes ☐ No

Jason Ludwig
TCEQ#MP0002278

Signature: 







PUMP TIMER

1211

20

10

10

12

6

0

6

12

6

12

6

12

6

12

6

12

6

12

6

12

6

12

6

12

6

12

6

12

6

12

6

12

6

12

6

12

6

12

6

12

6



