


I hereby certify that I have inspected the building site of the referenced home and acknowledge that the site has been fine graded and that the proper grades and drainage patterns have been established to include adequate fall away from the foundation as required by the approved grading plan, grading recommendations and/or soil report.

LOT NO. 63, BLOCK NO 23, NCB NO —
SUBDIVISION CREST RIDGE SUBDIVISION
UNIT 11, VOL. 9506, PAGE(S) 110
STREET ADDRESS 6743 BADGER PASS DR.
CITY —, BEXAR COUNTY, TEXAS.
SURVEYED FOR SAN ANTONIO TITLE CO. GF NO
BUYER(S)

LEGEND
F.I.P. : FOUND ½" IRON PIN
S.I.P. : SET ½" IRON PIN
P.I. : POINT OF INTERSECTION
P.C. : POINT OF CURVE
P.T. : POINT OF TANGENT
C.M. CONTROLLING MONUMENT

STATE OF TEXAS
COUNTY OF BEXAR

NOTES:
1 THE SUBJECT PROPERTY IS NOT SITUATED WITHIN ZONE "A" ACCORDING TO THE FLOOD INSURANCE RATE MAP, COMMUNITY PANEL NUMBER 480034-C 0017 F-E EFFECTIVE FEB. 16, 1996, DEFINED BY THE FEDERAL EMERGENCY MANAGEMENT AGENCY

2 BEARINGS ARE BASED ON THE RECORDED PLAT

THIS PROPERTY IS SUBJECT TO RESTRICTIVE COVENANTS RECORDED IN:
VOL 6002 PG 1180 VOL — PG —
VOL 7009 PG 1807 VOL — PG —
VOL — PG — VOL — PG —

STATE OF TEXAS REGISTERED HARDIT SINGH 4600 PROFESSIONAL LAND SURVEYOR

I HEREBY CERTIFY THAT THE ABOVE PLAT IS TRUE, CORRECT AND AN ACCURATE REPRESENTATION OF THE PROPERTY ACCORDING TO AN ACTUAL SURVEY MADE ON THE GROUND UNDER MY SUPERVISION AND EXCEPT AS SHOWN ABOVE THERE ARE NO VISIBLE DISCREPANCIES, CONFLICTS, PROTRUSIONS OR INTRUSIONS, OVERLAPPING OF IMPROVEMENTS, EASEMENTS, OR RIGHT-OF-WAY

THIS 17TH DAY OF AUGUST 19 98 A.D.

SURVEY ORDER NO. 98-0147506
SCALE: 1" = 20' DWN BY: KR CHK BY: L.A.
REV./UPDATED

SOUTH TEXAS ENGINEERING, INC.
CONSULTING ENGINEERS • LAND SURVEYORS
4606 CENTERVIEW SUITE 110 • SAN ANTONIO, TEXAS 78228 • TEL (210) 736-2648 • FAX (210) 736-2358