
5935 GLENHURST DR | HOUSTON, TX 77033

Renovation Highlights

From exposed framing to a fully renovated home

BEFORE	IN PROGRESS	AFTER
		
		
		

Scope of work

01 New roof	07 New paint
02 Approximately 80% of framing replaced	08 New flooring
03 New plumbing	09 New kitchen cabinets
04 New electrical wiring	10 New kitchen appliances
05 New air conditioning	11 Fully remodeled kitchen
06 All new drywall (Sheetrock)	12 Both bathrooms fully remodeled